1	LISA GOLLIN EVANS (MA SB # 200730) (Admitted <i>Pro Hac Vice</i>)	THE HONORABLE WILLIAM H. ALSUP
2	Earthjustice 21 Ocean Avenue	
3	Marblehead, MA 01945 (781) 631-4119	
4	levans@earthjustice.org	
5	JAN HASSELMAN (WSB #29107) (Admitted <i>Pro Hac Vice</i>)	
6	Earthjustice 705 Second Avenue, Suite 203	
7	Seattle, WA 98104	
8	(206) 343-7340 (206) 343-1526 [FAX]	
9	jhasselman@earthjustice.org	
10	Attorneys for Plaintiffs Sierra Club, Great Basin Resource Watch, Amigos Bravos, and	
11	Idaho Conservation League	
12	GREGORY C. LOARIE (CSB #215859) Earthjustice	
13	426 - 17 th Street, 5 th Floor	
14	Oakland, CA 94612 (510) 550-6725	
15	(510) 550-6749 [FAX] gloarie@earthjustice.org	
16	Local Counsel for Plaintiffs	
17	UNITED STATES DIST	RICT COURT
18	FOR THE NORTHERN DISTRI SAN FRANCISCO	
19	SIERRA CLUB, et al.,	Case No. 3:08-cv-01409-WHA
20		
21	Plaintiffs,) v.)	DECLARATION OF ELIZABETH CUMBERLAND
22	STEPHEN JOHNSON, et al.,	COMBERLAND
23	Defendants,	
24	and)	
25	SUPERFUND SETTLEMENTS PROJECT, et al.,	
26	Defendant-Intervenors.	
27		
28		Earthjustice
	DECLARATION OF ELIZABETH CUMBERLAND (Case No. 3:08-cv-01409-WHA)	705 Second Ave., Suite 203 Seattle, WA 98104 (206) 343-7340

5

9

7

11

15

27

I, ELIZABETH CUMBERLAND, declare and state as follows:

- 1. I am over the age of 21 and competent to testify to all matters contained herein.
- 2. I reside at 761 Martindale Falls, Martindale, Texas 78655. I was born in Kingsville, Texas and lived on the farm where Uranium Resources, Inc. ("URI") is mining for uranium until I reached adulthood. I have lived at 761 Martindale Falls, Martindale, Texas 78655 since 1997.
 - 3. I have been a member of the Sierra Club since 2007.
- 4. My family's farm is located in the heart of the Texas site of the Kingsville Dome in situ leach uranium mine owned and operated by URI.
- 5. Since 1988 when URI started actual mining, the groundwater on our land has been dangerous to drink or use for any purpose, the surface has lain dormant, toxic with radioactivity, and now the farmland is fenced in by URI, padlocked, posted with signs warning of radioactivity, and returning to brush mixed with broken wellheads which expose the groundwater to further contamination. To date, URI has not submitted an application to begin the restoration certification process, a process which takes a minimum of twelve months, but usually takes several years.
- 6. Our farmland in PAA2 has also lost ninety percent of its value in dollars. Much worse, the legacy of good farming established by our grandfather and father is now, instead, a danger to our neighbors' water wells, a hazard to migrating birds flying within the largest migratory route in the United States the Great Coastal Birding Trail, a threat of lowered land values to the whole neighborhood, and a "barren wasteland" according to the appraisal district.
- 7. At present, URI has three production areas, PAA1, PAA2, and PAA3. My family owns property in PAA2 and PAA3. In PAA2, my family owns the surface (not the minerals) of 80 acres, Farm Lots (1-8), Block 49, Kleberg Town and Improvement Co., Vol. 1, Page 34, Kleberg County, Texas.
- 8. Prior to mining, our land was farmed in cotton and grain. It was valued at \$938 per acre in 1988, also the year of our father's death. See Exhibit A (summary of property tax

values filed in probate records). Today, this same land is valued by the tax appraisal district at \$223 per acre. See Exhibit B (2008 property tax value). Other nearby land owned by my family facing the same highway has more than doubled in value to \$2,412 per acre. Specifically, eighteen acres located about one mile east, valued at \$982 per acre in 1988, are presently valued at \$2,412 per acre. See Exhibit C (2008 property tax value); see also Exhibit A (1988 property tax for Block 47, Lots (1), (2), (7) and (8)).

- 9. Our groundwater in PAA2, which was generally tested at 11 micrograms uranium per liter prior to mining, is now testing at approximately 3,300 micrograms uranium per liter.

 See Exhibit D (URI 1st QTR 2008 restoration progress report). This extremely high concentration (the EPA allows 30 micrograms uranium per liter in drinking, livestock, and irrigation water) persists, although URI reports to the Securities Exchange Commission that it has done restoration work since 2000. See Exhibit E (10-K/A filed 4/10/08; URRE reported at Edgar Online); see also Edgar Online for 10-K filed in prior years 2000-2007.
- 10. Even worse, URI makes claims that the groundwater was concentrated in uranium prior to mining and, therefore, even if it ultimately restores the water according to TCEQ rules, the water will be 172 times more concentrated in PAA2 than it was prior to exploration.
- 11. URI reports to its investors that so far it has spent \$3,179,000 for seven years of groundwater restoration work in PAA1 and PAA2. See Exhibit E (10-K/A filed 4/10/08 URRE reported at Edgar Online); see also 10-K filed in prior years 2000-20007. Yet, after years of pouring good water through the underground in situ mine (using groundwater flush and reverse osmosis treatment), the groundwater remains at very high levels of uranium in both production areas. In PAA1 it is 1,400 micrograms per liter, and in PAA2 it is 3,280 micrograms per liter, according to URI's 2008 report to the TCEQ. See Exhibit D (URI 1st QTR 2008 restoration progress report).
- 12. In the year 2000, URI threatened bankruptcy. On August 9, 2000, TCEQ staff attorney Don Redmond told me that the total amount in bonds allocated for restoration of the groundwater at the Kingsville Dome mine ("KVD") (which encompassed PAA1 and PAA2) was

\$1,741,542.00. At that time, the TCEQ and the Texas Department of Health ("TDH") held restoration bonds for PAA1 and PAA2. See Exhibit F (memo based on conversation with TCEQ attorney Don Redmond). As a result of URI's continued threats, in 2000 the TCEQ and TDH entered into an agreement with URI whereby all collateral for the restoration bonds was released to URI, and it agreed to begin restoration of both production areas.

- 13. Now, with restoration of the groundwater nowhere in sight, and no action taken to even initiate the restoration certification process, URI presently reports it has spent almost 3.2 million dollars trying to restore the groundwater. Yet, the TCEQ had required only \$1.7 million in bonding for groundwater restoration. Clearly, the bond amount was not even close to what has been required so far.
- 14. URI is presently mining in PAA3 where there is no reason to expect a different outcome. In PAA3, my family owns the surface (not the minerals) of 160 acres of Farm Lots (11-14), Section 41, Kleberg Town & Improvement Co., Kleberg County, Texas. Also in PAA3, my family owns the surface and an <u>undivided</u> interest in minerals in an additional 160 acres of Farm Lots (3-6), Block 48, Kleberg Town and Improvement Co., Kleberg County, Texas. In Texas, one mineral owner cannot prevent other mineral owners of the same property from developing their minerals. In late 2006, my brothers ratified an expired mineral lease for these 160 acres because URI was preparing to mine on our land without a ratification since it had leases from other mineral owners.
- 15. The U.S. Environmental Protection Agency errs when it does not require facilities that handle hazardous substances, like uranium mines, to provide proper bonding consistent with the degree and duration of risk associated with their activities. Restoration bond amounts should be based on the amount of money required to return the groundwater to the <u>actual</u> baseline, determined by an independent agency through accurate and statistically valid measurements.
- 16. If the U.S. EPA requires uranium mines, like URI, to maintain financial assurance sufficient to return the water to the actual baseline, restoration of the groundwater in my community would occur and URI would have greater incentive to prevent the degradation of

groundwater while mining in PAA3.

Pursuant to 28 U.S.C. § 1746, I declare under penalty of perjury that the foregoing is true and correct to the best of my knowledge. Executed this 28 day of August, 2008, at Kingsville, Texas.

Elizabeth Cumberland

DECLARATION OF ELIZABETH CUMBERLAND (Case No. 3:08-cv-01409-WHA) -4-

Earthjustice 705 Second Ave., Suite 203 Seattle, WA 98104 (206) 343-7340

Case 3:08-cv-01409-WHA Document 74-2 Filed 09/04/2008 Page 1 of 2

EXHIBIT A

	OF RECORDS 10	*						*
80.000 V	49-K T & I CO	W PT E 49-K 200 AC 1-8 GED#5633-4000	•	75,050	14,440	902 D3)1102101 CUMBERLAND W E	290004901102101
53.330 V	48-K T & I CO	W53+33 48-K AC 3-6 GED#5628-1000	•	47,380	10,800	902 D1	5100101 CUMBERLAND W E	290004805100101
19.300 "	47-K T & I CD SYM 5 -3000	PT 1,2 47-K 7,8 S GED#5619-3000	O	17,760	3,790	902 DI)1115101 CUMBERLAND W E	1409-WHA 290004701115101
1.000 1	47-K T & I CO SYM 5	PT 1,2 7,8	63,500	0 E1	1,000	902 E1	1105101 CUMBERLAND W E	290004701105101
53,330 (+1-K T & I CO -3000	E53.33 41-K AC11-14 GED#5548-3000	0	41,780	7,420	902 D3	1101101 CUMBERLAND W E	cument 7 ² 290004111101101
40.000 V	40-K T & I CO	540 AC 13-14 GEU#5545	•	35,050	6,870	902 D3	3100101 CUMBERLAND W E	S 290004013100101
ä	40-K T & I CU	W95 AC 40-K 1-8 GEO#5543-3000	•	92,250	19,490	902 03	4100101 CUMBERLAND W E	led 09/04 290004004100101
50.330 ×	22K T & I CO	W50,33 22K 11-14 DED#5452-8000	0	50,330	11,830	901 D3	1100192 CUMBERLAND W E	3)290002211100192
10.000 /	22K 7 & 1 CO SYM D 6000	PT 7 22K S' GEO#5449-6000	•	10,000	2,280	9 01 03	7102192 CUMBERLAND WE	Page 2 290002207102192
62,000 -	20-K T & I CO N62 AC OF 25 1-2000	20-K N 0ED#5412-2000	٥	## 000 T	11,670	902 D1	5101101 CUMBERLAND W E	290002025101101
ACRES	DESCRIPTION #1		MPIMPROVEMENT LEGAL OV MARKET	LIED G	A4 HARKET	SCH REA REAL GOVMARKET	DENER NAME	CONTROL
	s grang para dalah Sibil daba 1860. Zaidi wasa 1866 Mah Mahi dalah maha ishadi dabah basa dasid			***************************************	CONTRACTOR OF THE PARTY OF THE	2.ETT 2 A	· · · · · · · · · · · · · · · · · · ·	TOR COME LEGISLA

Case 3:08-cv-01409-WHA Document 74-3 Filed 09/04/2008 Page 1 of 3

EXHIBIT B

PIDN: 14456 GEO: 290004901102101

TaxNetUSA:	Kleberg	County	Property	Information
------------	---------	--------	-----------------	-------------

Owner Name	CUMBERLAND W E TRUST	Entity Code	Entity Name	Tax Rate 2007
		GKL	Kleberg County	0.646400
Mailing	% DALE CUMBERLAND CO-TRUSTEE 1421 SLEEPY HOLLOW	SRC	Ricardo ISD	1.170000
Address	NEW BRAUNFELS, TX 78130-	WST	South Texas Water Authority	0.056880
Location	CO R D 1080	CAD		
	K T & I CO, BLOCK 49, LOT W PT E200 AC 1-8, 50%		Total	1.87328
Legal	UNDIVIDED INTEREST, (DAC: 40.00), ACRES 80. 50% UNDIVIDED INTEREST, (DAC: 40.00)	*Total Es	\$167.10	

Data up to date as of Aug 12, 2008 including 2008 Certified values.

Note: The Total Estimated Taxes are provided as a courtesy and should not be relied upon in making financial or other decisions. *Tax amount does not include any abatements or exemptions.

		,,	
Property Details		Value Information	2008 Certified
Deed Date	//	Land Value	\$8,920.00
Deed Volume		Improvement Value	\$0.00
Deed Page		AG Value	\$0.00
Docket No.		AG Productivity Value	\$0.00
Exemptions		Timber Value	\$0.00
Freeze Exempt	F	Timber Productivity Value	\$0.00
ARB Protest	F	Assessed Value	\$8,920.00
Agent Code	0	Total Value	\$8,920.00
Land Acres	80.0000		
Block	49		
Tract or Lot	W PT E200 AC 1-8		
Abstract Code	S2900		
Neighborhood Code			
Improvement Information			
Improvement ID	State Category	Description	า

Segment Information

Area	Effective Year Built	Class	Description	Type Code	Seg ID	Imp ID
0	Total Living Area					

Land Information

Land ID	Type Code	SPTB Code	Homestead	Size-Acres	Front	Depth	Size-SQFT
4664	BRNW	D2	F	20.000	0	0	871,200
4665	BRNW	D2	F	13.500	0	0	566,280
4666	BRNW	D2	F	30.000	0	0	1,306,800
4667	BRNW	D2	F	12.000	0	0	522,720
4668	BRNW	D2	F	4.500	0	0	174,240

Improvement Sketch

Page 3 of 3

There is no sketch data available for this parcel.

EXHIBIT C

PIDN:	25414	GEO:	290004	/011	15101

Owner Name	CUMBERLAND BYRON L	Entity Code	Entity Name	Tax Rate 2007
		GKL	Kleberg County	0.646400
Mailing Address	P O BOX 493 PORT LAVACA, TX 77979-	SRC	Ricardo ISD	1.170000
Location	1118 FM RD	WST	South Texas Water Authority	0.056880
		CAD		
Legal	K T & I CO, BLOCK 47, LOT PT 1, 2, 7, 8, ACRES 18.3, (SYM 5)		Total	1.87328
	(SYM 5)	*Total Es	\$826.87	

Data up to date as of Aug 12, 2008 including 2008 Certified values.

Note: The Total Estimated Taxes are provided as a courtesy and should not be relied upon in making financial or other decisions. *Tax amount does not include any abatements or exemptions.

Property Details		Value Information	2008 Certified
Deed Date	02/05/2007	Land Value	\$0.00
Deed Volume	354	Improvement Value	\$0.00
Deed Page	935	AG Value	\$44,140.00
Docket No.		AG Productivity Value	\$2,420.00
Exemptions		Timber Value	\$0.00
Freeze Exempt	F	Timber Productivity Value	\$0.00
ARB Protest	F	Assessed Value	\$44,140.00
Agent Code	0	Total Value	\$44,140.00
Land Acres	18.3000		
Block	47		
Tract or Lot	PT 1, 2, 7, 8		
Abstract Code	S2900		
Neighborhood Code			

Improvement Information

Improvement ID **State Category** Description

Segment Information

Imp ID	Seg ID	Type Code	Description	Class	Effective Year Built	Area
					Total Living Area	0

Land Information

Land ID	Type Code	SPTB Code	Homestead	Size-Acres	Front	Depth	Size-SQFT
16034	IMPR2	D1	F	6.610	0	0	287,932
132995	IMPR3	D1	F	11.690	0	0	509,216

Improvement Sketch

There is no sketch data available for this parcel.

Case 3:08-cv-01409-WHA Document 74-5 Filed 09/04/2008 Page 1 of 5

EXHIBIT D

Document 74-5

Filed 09/04/2008 Page 2 of 5

URI, INC.

(A Subsidiary of Uranium Resources, Inc.)

Rosita Operations HC01, Box 50 San Diego, Texas 78384 Telephone: (361) 279-3307 Fax: (361) 279-2260 650 South Edmonds Lane Suite 108 Lewisville TX, 75067 Telephone: (972) 219-3330 Fax: (972) 219-3311 Kingsville Operations 641 East FM 1118 Kingsville, Texas 78363 Telephone: (361) 595-5731 Fax: (361) 595-0403

April 14, 2008

Texas Commission on Environmental Quality (MC172)

Office of Compliance and Enforcement

Homeland Security

Attention: Dale Kohler

12100 Park 35 Circle (Bldg "C")

P.O. Box 13087

Austin, Texas 78711-3087

FECTOR

LDR 2 3 7008

DENTRAL FILE FIG. DIV

RE: Progress Report (1st QTR 2008) for Restoration Activities at URI's Kingsville Dome and Rosita Uranium Facilities in South Texas

Dear Mr. Kohler:

Attached is the quarterly report covering restoration progress at the Kingsville Dome and Rosita mines. This is a complimentary report, rather than required, since the Groundwater Restoration Performance Agreement with the TCEQ and the DSHS has expired. This document covers the progress for the calendar quarter ending March 31, 2008.

As in the past, I have included two copies of the report so that you may file one in each of the Kingsville and Rosita files. I have also included an additional copy for Muhammadali Abbaszadeh. Should you have any questions concerning this report, please contact me at the Kingsville office.

Sincerely.

Ronald E. Grant

Reservoir Engineer

URI. Inc.

cc: M. Buckley. TCEQ- Corpus

Ron Grant

Muhammadali Abbaszadeh, TCEQ - Austin

vidilallilladai

Uranium Resources, Inc Quarterly Restoration Progress Report Kingsville and Rosita Properties

This is the First Quarter, 2008 URI Restoration Report for URI's Kingsville Dome and Rosita Projects. It covers groundwater restoration activities at URI's uranium mine facilities in South Texas for the period January 1, 2008 through March 31, 2008. During the first quarter of 2008, URI treated 110.14 million gallons of groundwater at the two South Texas facilities.

KINGSVILLE

During the quarter, KVD treated 70.92 MM gallons as compared to the minimum requirement of 61.04 MM gallons. This is 9.88 million gallons more than the minimum requirement for this quarter.

Wellfield Operations

We are now restoring wells in WF-6 which is the only remaining wellfield to be restored in PAA-2 North of F.M. 1118. Individual well plots and baseline data for PAA2 may be seen in the Appendices. Baseline data for PAA1 and PAA2 is summarized in Table No. 1 and Table No. 2 respectively.

KINGSVILLE RO OPERATIONS

While in operation, the RO processed 61.83 MM gallons of groundwater and sent 46.64 MM gallons of clean product water back to the field. Conductivities for product water averaged 1148 uhmos based on a feed average Reject for the month averaged 24.6% of feed. Detailed of 2193 uhmos. operating data can be seen in the Appendices. At the end of this quarter there have been operational problems with the RO. Tuesday 3-25-08, the differential pressure on the first stage for the RO begin rising above its normal operating pressure of 25 psi. After three days, the differential pressure was in the 70 to 90 psi. range, and the flow capacity for the RO was reduced to approximately 50% of its normal capacity. This was occurring at the same time that the feed pump for the RO began showing signs of failure, and it was not certain at that time which was the major contributor to the loss of flow. The feed pump was disassembled on Friday, 3-28-08 and required replacement of the impeller which was done that very day. Flow was erratic over the weekend, and on the evening of Monday, 3-31-08, it was discovered that the RO had failed internally and was passing water without treatment. It was shut in at that time. presently in progress and all membranes have been removed from their tubes and are undergoing inspection.

WDW 248

WDW-248 injection for the 1st Quarter, 2008 was 24.29 MM gallons. There have been no problems with WDW 248 during this quarter.

TABLE No. 1 KINGSVILLE DOME MINE COMPARISON OF PAA1 BASELINE WELLS TO LIMITS

		1		1		1	00:1	5.7
		Ec	U308	a	Ca	HCo3	SO4	Nb
	рН	(umhos)	(mg/l)	(mg/l)	(mg/I)	(mg/l)	(mg/l)	(mg/l)
BL-EX-1			W	ell Aband	oned			
BL-EX-2	7.4	1485	2.1	199	93	342	226	1.50
BL-EX-3	7.4	1635	2.4	246	135	368	226	0.95
BL-I-1	7.3	1588	0.4	246	135	387	426	3.70
BL-I-2	8.0	1748	0.2	233	129	368	275	0.05
BL-I-3	7.8	1935	2.5	246	117	406	306	0.06
BL-1-4	7.4	1686	0.4	206	75	366	318	2.10
BL-I-5	7.1	1760	3.4	186	304	431	426	2.30
BL-I-6	Insufficient Sa	ample						
BL-I-7	7.7	1826	0.3	246	87	366	368	3.30
BL-I-8	7.1	1400	1.3	133	210	393	321	0.94
BL-I-9	7.0	1655	3.1	93	234	381	527	5.00
BL-I-10	7.2	1456	2.2	199	99	342	197	4.90
BL-I-11	Insufficient Sa	ample						
BL-I-12	7.3	2840	0.2	266	195	444	440	2.70
BL-I-13	7.7	1567	0.3	219	150	317	240	0.19
Comparison to Restoration Tal	ole Values		- 5					
Well Average	7.4	1737	1.4	209	151	378	330	2.13
Restoration Table	8.74	1717	0.164	234	20.8	268	204	0.06
Comparison to Restoration Rai	nge Table Vali	ues						
Well Average	7.4	1737	1.44	209	151	378	330	2.13
Restoration Range Table (High)	9.50	2100	1.89	352	74	505	310	0.84
Restoration Range Table (Low)	7.37	1470	0.002	196	5.15	142	13	<.01

Table No. 2

KINGSVILLE DOME MINE

COMPARISON OF PAA2 BASELINE WELLS TO LIMITS

\\\\	На	Ec (umhos)	U3O8 (mg/l)	CI (mg/l)	Ca (mg/l)	HCO3 (mg/l)	SO4 (mg/l)	Mo (mg/l)	
Well	1 bu	(uninos)	(mgn)	(mgn)	(1119/1)	(1119/1)	(11.19/1/	(11.5.7)	
BL 1491	8.0	1573	0.2	219	246	330	206	0.03	
BL 547	- 7.6	1972	6.9	246	117	409	567	3.10	
BL 1240	8.0	1362	3.9	179	51	342	110	2.00	
BL 1265	7.3	1445	2.1	206	102	336	179	3.90	
BL 1047	Insufficient Sample								
Comparison to Restoration	n Table Values	S							
Well Average	7.7	1588	3.28	213	129	354	266	2.26	
Restoration Table	7.37-8.66	1662	1.89	224	25.3	327	224	0.38	
Comparison to Restoration Range Table Values									
Well Average	7.7	1588	3.28	213	129	354	266	2.26	
Restoration Range Table (High)	9.50	2100	1.89	352	74	505	310	0.84	
Restoration Range Table (Low)	7.37	1470	0.002	196	5.15	142	13	<.01	

ROSITA

Water treated for the first quarter, 2008 totaled 39.22 MM gallons. This is less that the full capacity for Rosita's RO due to our impending shutdown of restoration activities at our Rosita property. In just a few more weeks, restoration activities will cease in PAA-1, PAA-2 and PAA-3. At that point, restoration will be declared compete in PAA-1 and PAA-2, and stabilization will commence. PAA-3, however, is presently being drilled and cased for WF-8. When production ceases in WF-8, restoration operations will once again resume and stabilization can commence when that restoration is complete.

RO Operations

When in service, the Rosita RO processed over 37.24 MM gallons of groundwater and sent 24.59 MM gallons of product back to the field. Conductivities for product water averaged 1107 uhmos based on a feed average of 3035 uhmos. Reject for the month averaged 34.0% of feed. Detailed operating data can be seen in the Appendix.

Case 3:08-cv-01409-WHA Document 74-6 Filed 09/04/2008 Page 1 of 3

EXHIBIT E

10-K/A filed 4/10/2008 Uranium Resources, Inc (URRE)

Item 2. Properties.

South Texas

We currently control 3 major properties in the state of Texas. The Kingsville Dome, Rosita and Vasquez properties are shown in Figure No. 2.1 and are described below.

Figure No 2.1. Texas Properties Location Map

■ FPRIVATE"TYPE=PICT;ALT=GRAPHIC"

Kingsville Dome (Figure 2.2)

The Property. The Kingsville Dome property consists of mineral leases from private landowners on about 2,354 gross and net acres located in central Kleberg County, Texas. The leases provide for royalties based upon a percentage of uranium sales of 6.25%. The leases have expiration dates ranging from 2000 to 2007. We hold most of these leases by production; and with a few minor exceptions, all the leases contain clauses

that permit us to extend the leases not held by production by payment of a per acre royalty ranging from \$10 to \$30. We have paid such royalties on all material acreage. Mineralization is found in the Goliad formation at depths of 600 to 750 feet.

Production History. Initial production commenced in May 1988. From then until July 1999, we produced a total of 3.5 million pounds. Production was stopped in July 1999, because of depressed uranium prices. We spent about \$8.0 million in capital expenditures at Kingsville Dome in 2007. We

26

resumed production at Kingsville Dome in April 2006 and produced 338,100 pounds of uranium in 2007. We spent about \$10.4 million in capital expenditures and produced 94,100 pounds of uranium in 2006. We believe that there is a significant quantity of uranium remaining at Kingsville Dome.

Permitting Status. A radioactive material license and underground injection control permit have been issued. As new areas are proposed for production, additional authorizations under the area permit are required. Approval of our Production Area Authorization #3 was received in February 2006 which allowed for the start-up of production at Kingsville Dome in April 2006. See " **Legal Proceedings**."

Restoration and Reclamation. During 2007, we conducted restoration activities as required by the permits and licenses on this project, spending approximately \$595,000 on such activities. In 2006 and 2005, we spent about \$321,000 and \$358,000 in restoration costs.

Case 3:08-cv-01409-WHA Document 74-7 Filed 09/04/2008 Page 1 of 3

EXHIBIT F

fax no. 512-475-3741

Rick Lowerre fax no.

Craig Holmes fax no. 512-250-0727

From: Elizabeth Cumberland

tel. no. 512-805-0566

Date: August 9, 2000

Re: Bond amounts, agencies, purposes, and site allocation which were provided today by staff attorney Don Redmond, TNRCC.

\$ 233,693.00	TNRCC	plug & abandonment	Kingsville
\$ 390,123.00	TNRCC	plug & abandonment	Kingsville
\$ 91,149.00	TNRCC	plug & abandonment	Kingsville
\$ 125,000.00	TNRCC	plug & abandonment	Kingsville
<u>\$1,741,542.00</u>	TDH o	ground water restoration	KVD
\$ 699,458.00	TDH	surface restoration	Kingsville & Rosita
\$ 92,076.00	TNRCC	plug & abandonment	Rosita
\$ 227,779.00	TNRCC	plug & abandonment	Rosita
\$ 100,299.00	TNRCC	plug & abandonment	Rosita
\$ 126,000.00	TNRCC	plug & abandonment	Rosita
\$1,909,643.00	<u>TDH</u>	ground water restoration	Rosita
TOTAL \$5,736	5,762.00 minu	. \$ 546,154 (Rosita) = \$	5,190,608.00

Case 3:08-cv-01409-WHA Document 74-7 Filed 09/04/2008 Uranium Resources, Inc. Restoration Expenditures July 1, 2000 - December 31, 2001

	<u>Jul-00</u>	<u>Aug-00</u>	<u>Sep-00</u>	Oct-00	<u>Nov-00</u>	<u>Dec-00</u>	<u>Jan-01</u>	Feb-01	<u>Mar-01</u>
KVD Direct Restoration Rosita Direct Restoration Rosita Restoration Capital RAV, MSP & THE	57,503 38,567 26,850	57,503 44,267 68,630	57,503 44,267 5,000	57,503 44,267	57,503 44,267	63,503 50,267	57,503 42,898	57,503 42,898	57,503 42,898
plus 20% Burden rate**	17,220	17,220	17,220	17,220	17,220	17,220	17,220	17,220	17,220
Total	\$140,140	\$187,620	\$123,990	\$118,990	\$118,990	\$130,990	\$117,621	\$117,621	\$117,621
Quarterly Totals			\$451,750			\$368,970			\$352,863
Cummulative Expenditures	\$140,140	\$327,760	\$451,750	\$570,740	\$689,730	\$820,720	\$938,341	\$1,055,962	\$1,173,583
	<u>Apr-01</u>	May-01	<u>Jun-01</u>	<u>Jul-01</u>	<u>Aug-01</u>	<u>Sep-01</u>	Oct-01	Nov-01	Dec-01
KVD Direct Restoration Rosita Direct Restoration Rosita Restoration Capital	Apr-01 57,503 42,898	May-01 57,503 42,898	Jun-01 57,503 42,898	Jul-01 57,503 42,898	Aug-01 57,503 42,898	<u>Sep-01</u> 57,503 42,898	Oct-01 57,503 42,898	Nov-01 57,503 42,898	Dec-01 63,503 48,898
Rosita Direct Restoration	57,503	57,503	57,503	57,503	57,503	57,503	57,503	57,503	63,503
Rosita Direct Restoration Rosita Restoration Capital RAV, MSP & THE	57,503 42,898	57,503 42,898	57,503 42,898	57,503 42,898	57,503 42,898	57,503 42,898	57,503 42,898	57,503 42,898	63,503 48,898
Rosita Direct Restoration Rosita Restoration Capital RAV, MSP & THE plus 20% Burden rate**	57,503 42,898 17,220	57,503 42,898 17,220	57,503 42,898 17,220	57,503 42,898 17,220	57,503 42,898 17,220	57,503 42,898 17,220	57,503 42,898 17,220	57,503 42,898 17,220	63,503 48,898 17,220

Page 3 of 3

^{**}NOTE: 100% OF RAV, 16 hrs/week for MSP, & 8 hours/week for THE